

Photo 11 - Breaching of unreinforced blockwall (David)




Photo 12 - The very favourable geometry saves this very modest house from any damage (Hugo)




Photo 9 - Longitudinal splitting of timber rafters (Hugo)




Photo 10 - Almost 100% loss of windows in the hospital. (Gilbert)