

Photo 5 - Destruction of reinforced-concrete frames (David)




Photo 7 - Loss of corrugated, metal, roof sheets (Gilbert)




Photo 6 - Several lattice towers of this type collapsed in David, Gilbert and Hugo (David)




Photo 8 - Loss of precast-concrete, barrel tiles (Andrew, Florida)