



Figure 16. A house near Lake Atitlan viewed westward from the Panajachel River, illustrating lateral spread ground cracks (A), resulting cracks in the retaining wall (B), damage to the house (C), and subsidence (D).